

**ZONE TWO
PUBLIC SIDEWALK IMPROVEMENT NOTICE**

PLATTED SUBDIVISIONS	SWR YR	PARCEL ID	# LOTS
Aziz Estates Sub #1 (1993)	SWR14	096-02-0001 thru 0005	5
Aziz Estates Sub #2 (1996)	SWR14	096-05-0006 thru 0045	40
Brookside Village Sub #1 (1974)	SWR04	093-01-0001 thru 0226	226
Brookside Village Sub #2 (1976)	SWR04	093-02-0227 thru 0343	117
Brookside Village Sub #3 (1978)	SWR04	093-04-0344 thru 0497	154
Brookside Village Sub #4 (1991)	SWR04	096-01-0498 thru 0530	33
Brookside Village Sub #5 (1994)	SWR04	096-03-0531 thru 0623	93
Brookside Village West (1978)	SWR04	093-03-0001 thru 0091	91
Camden Park (1995)	SWR14	094-06-0001 thru 0034	34
Dasher Heights (1998)	SWR14	096-06-0001 thru 0106	106
Holiday Park Sub #1 (1965)	SWR02	001-01-0001 thru 0207	207
Holiday Park Sub #2 (1966)	SWR02	004-01-0208 thru 0470	263
Holiday Park Sub #3 (1968)	SWR02	001-02-0471 thru 0530	60
Westfield Estates Sub (1997)	SWR14	094-07-0001 thru 0079	79
		TOTAL # LOTS	1508

PERIMETER OF ZONE TWO:

South side of Joy Road, West side of Hannan Road, North side of Van Born Road & the East side of Haggerty Road

NOTE:

The area of zone two includes all commercial and residential parcels that are located along a public road right-of-way.

2016 SIDEWALK REPAIR AND GAP PROGRAM

Canton Township Engineering Services will be performing sidewalk inspections in zone two to obtain preliminary quantities for replacement. Sidewalks that need replacement will be denoted with one of two (2) colors.

GREEN - Denotes the property owner's responsibility for the cost of replacement.
RED - Denotes Canton's responsibility for the cost of replacement.

Defective sidewalk located within a drive may require driveway approach slabs directly adjacent to be marked for repair (owner's responsibility). Should an owner have a defective concrete drive approach, located between the sidewalk and curb, and no defective sidewalk, upon request only (owner's responsibility) we can include with the sidewalk repair program.


In an effort to complete the inspections in a timely fashion, we ask that if there is a concern regarding responsibility that the property owner wait to contact Engineering Services until the Fall of 2015 or Spring of 2016 to schedule an appointment to review the markings. The paint dots are preliminary markings during the initial walk thru of the subdivision and along the public right-of-way. There may be some revisions that occur upon measuring the quantities and determining the responsibilities.

Additional information will follow when you receive your notification letters in the Spring of 2016. The following represents a tentative schedule:

- NOTIFICATION LETTERS (Estimated Cost & Quantity) - Spring 2016
- PUBLIC HEARING - Spring 2016
- CONSTRUCTION - 60 Days After the Public Hearing
- INVOICES - Fall/Winter 2016

Please review the sidewalk ordinance and our website for commonly asked questions at www.canton-mi.org. The sidewalk ordinance section is in Chapter 62, Article 2, and Section 62-31/38 inclusive.

**Canton Township
2016 Sidewalk Repair Program
ZONE 2
North of Cherry Hill Road**



**Canton Township
2016 Sidewalk Repair Program
ZONE 2
South of Cherry Hill Road**

